

ESTIMATES FOR THE RENOVATION WORK OF MAGWI HEALTH CENTRE (CATHOLIC DIOCESE OF TORIT)

A) FACILITY BLOCK.

S/N	DESCRIPTION OF MATERIALS	UNIT	QUANTITY	RATE, USD	AMOUNT, USD
01	Floor and veranda. (Some worn- out parts of the floor and veranda are to be demolished and new screeding is to be done).				
	 Provide cement of high quality 	Bag	15		
	 Provide building sand preferably river sand. 	Trip	2		
	 Provide water for the work 	Liter	1200		
	 Provide red oxide paint for the floor. 	Liter	100		
	 Provide rollers and soft brush 	No	6		
	Total to collection				
02	Doors. Four wooden doors are to be removed and changed with metallic one and all the eight door locks is to be changed.				
	 Provide motish door locks heavy duty. 	No	8		
	 Metallic doors 	No	4		
	 Provide oil paint for painting the doors. 	Liter	16		
	Total to collection				
03	Windows. All the broken glasses from some windows are to be				
	removed and fix in new ones.				
	 Provide good quality glass sheet transparent 4mm 	Sheet	3		
	 Patty set 	Kilo	20		
	 Silicon glue 	Tube	4		

	Ducy ide this set for solving	l itan		
	 Provide thinner for mixing patty 	Liter	5	
	 Oil paint for painting the 			
	windows	Liter	20	
	Total to collection			
04	Ceiling board. All the damage			
	boards are to be removed and			
	nail in new board of good quality,			
	1200mmx2400mm soft board.			
	 Provide soft board 			
	1200mmx2400mm.	Piece	105	
	 Ceiling nails 	Kilo	30	
	 Provide under coat paint 	Liter	120	
	 Provide vinyl silk brilliant 			
	white for final coat on the			
	ceiling board.	Liter	100	
	✤ Rollers	No	4	
	Total to collection			
05	Deinting of the well both Internal			
05	Painting of the wall both Internal			
	and External surfaces. Prepare			
	the wall by sand papering it well and			
	ready to receive paint.	N.4	0	
	Provide sand paper	M	8	
	Provide rollers	No	6 4	
	 Soft brushes Provide emulsion paint for 	No	4	
	 Provide emulsion paint for under coat for both internal 			
	and external wall surfaces.	Litor	120	
		Liter	120	
	 Provide silk vinyl for final coat on the internal wall 	Liter	100	
	surfaces	Liter	100	
	 Surfaces Provide weather guard paint 			
	for the external wall surfaces	Liter	100	
	Total to collection	LILEI	100	
06	Roof structure. There are many			
	points on the roof that leaks,			
	proper checking is to be done			
	and mending those spots one at			
	a time.			
	♦ Glue/bondex	Tin	20	
	 Provide rubber watchers 	Packet	12	
	 Provide fascia board 	Piece	20	
	 ♦ Nails 	Kilo	10	
	 ◆ Paint 	Liter	16	
	Total to collection			
L		1		

S/N	DESCRIPTION	UNIT	QUANTITY	RATE, USD	AMOUNT, USD
01	Building and reinforcing the side of the wall that was damaged or broken. Provide support and under pining to				
	area broken.				
	 50mmx100mm Timbers for support 	Piece	6		
	 Provide well burnt clay bricks 	Piece	189		
	 Building sand 	Trip	1		
	✤ Cement	Bag	4		
	 Water for the work 	Liter	500		
02	Provide one window	Item	1		
03	Painting work. Prepare the surface clean to receive the paint both internal and external wall.				
	 Sand paper 	М	2		
	 Under coat paint 	Liter	40		
	 Silk vinyl paint 	Liter	20		
	 Weather guard 	Liter	20		
	✤ Roller	No	2		
	✤ Brush	No	2		
	 Oil paint 	Liter	8		
	Total to collection				
C)	GATE WORK. One side of the gate is broken and is to be welded (fabricated) and painted;	Item	1		